CHRIS D JONES 88 E HAMLIN ST SEATTLE, WA 98102

Re: Project #6703105-CN

Correction Notice #2

Review Type ORDINANCE

Project Address 1715 14TH AVE

Date January 17, 2020

Contact Phone (206) 899-2939

SEATTLE, WA 98122

Contact Email CHRIS@CHRISTOPHERJONESARCHITECTS. Address Seattle Department of Construction and

SDCI Reviewer Model SanchezInspectionsReviewer Phone (206) 233-2539700 Fifth AveReviewer FaxSuite 2000Reviewer Email Miguel.Sanchez@Seattle.govP.O. Box 34019

Owner GLASS HOUSE PROPERTIES LLC

Corrections also apply to Project(s)

Reviewer's note to the Applicant

After review of your project I found that following items need to be addressed. If you feel any of these items are shown on the plans and I may have missed them, please point that out and I will recheck the information. Once you ve completed the correction items and clearly identified them (please cloud revisions) on the drawings re-submit your project to DPD per the attached instructions. If you have any questions please do not hesitate to call. Seattle building codes can be accessed on line under 'Codes We Enforce' at: http://www.seattle.gov/dpd/codesrules/default.htm

Applicant Instructions

Please click on the following link to learn "How to Respond to a Correction Notice". If the 3-step process outlined in this document is not followed, there may be a delay in permit issuance and there is a potential for penalty fees.

For instructions on **uploading corrected plans through your portal**, follow this link: <u>How to Upload a Document to an Existing</u>

Note that you will not be able to upload corrected plans until all reviews are completed and the project's status is "Corrections Required".

Codes Reviewed

This project has been reviewed for conformance with one or more of the following codes: 2015 Seattle Building Code (SBC); 2015 Seattle Residential Code (SRC); Grading Code (SMC)

Corrections

TOWNHOUSE CORRECTION ITEMS CYCLE 1.

1. PREVIOUS CYCLE.

FYI - NO CORRECTION RESPONSE REQUIRED.

2. RESOLVED EXCAVATION.

Project #6703105-CN, Correction Notice #2

Seattle, WA 98124-4019

3. TOWNHOUSE UNIT SEPARATION.

SRC R302.2.1.

Townhouse unit separations shall be vertically continuous from foundation to the underside of the roof sheathing. Revise the following:

- 1). (A3.0) Wall assembly W8 does not meet UL 305. You need to specifically specify 5/8" M-Glass or revise the assembly to specify another material that meets the requirements of this approved fire rated assembly.
- 2). (A2.5) At the roof plan between units 4 &5 specify how the two 1-HR assembly is continuous to the top of the stairway penthouse. Provide a section detail to clearly show this separation.

PARTIALLY RESOLVED.

(A2.4-A2.5) Revise the floor plan fire retardant treated plywood notes to specify "no openings or penetrations in the roof within 4-feet of the common walls".

4. RESOLVED.

UNDER STAIR SPACE.

SRC 302.7.

5. RESOLVED.

SMOKE ALARMS.

SRC R314.3.

6. RESOLVED.

CARBON MONIXIDE ALARM.

SRC R315.1.

7. RESOLVED.

ROOF DRAINS.

SRC R903.4.

DUPLEX CORRECTION ITEMS CYCLE 1.

8. RESOLVED.

UNIT SEPARATION.

SRC R302.3.

9. RESOLVED.

MINIMUM ROOM AREAS.

SRC R304.1, R304.2.

10. RESOLVED.

EGRESS WINDOW.

SRC R310.

11. RESOLVED.

OPERABLE WINDOW

SRC R312.2.1.

12. RESOLVED.

ROOF DRAINS.

SRC R903.4.

Revised Schedule	Addition to Previous Schedule	2015 SBC (Struct) and SRC (Arch)
------------------	-------------------------------	----------------------------------



SDCI Statement of Structural Special Inspection

Project Number 6703105-CN
Project Address 1715 14TH AVE
SEATTLE, WA 98122

Architect Engineer **Date** 1/17/2020 4:25:48 PM

SDCI Plan Miguel Sanchez

Examiner Architect Phone

Inspection Agency Phone

Engineer Phone

Prior to issuance of a building permit, the owner, architect, or engineer acting on behalf of the owner shall appoint an inspection agency and shall sign and submit this form to the building official.

Property Owner, Architect, or Engineer Signature

I hereby certify that the engineering firm and inspection agency named below has been engaged to perform the special inspections outlined below as required by the Seattle Building Code. It is the responsibility of the owner or the owner's designee to notify the inspection agency or observer in a timely manner when the inspections listed below are required.

Signature Title Date Phone

Required Special Inspections

Inspection Agency Name

OTTO ROSENAU AND ASSOCIATES (206) 725-4600

Inspection Type

Description

- 1. Epoxy Grouted Anchor Bolt Installation
- 2. Mechanical Anchor Bolt Installation

Call (206) 684-8860 to schedule a pre-construction conference before the start of construction